






[BUILDING RELATIONSHIPS,
DESIGNING SOLUTIONS.]

Plate 7A.
Problem Areas Map
Countywide Act 167
Crawford County, Pennsylvania

- Problem Areas
- Stormwater Management Facilities
- Major Streams
- Minor Streams
- Water Bodies
- Limited Access
- Highway
- Major Road
- Local Road
- Municipal Boundaries
- County Boundaries

Act 167 Watersheds
Detailed Watershed Study

- Conneaut Outlet (1993 Act 167)
- French Creek
- Oil Creek

General Watershed Study

- Ashtabula River
- Brokenstraw Creek
- Conneaut Creek
- Cussewago Creek
- Little Shenango River
- Muddy Creek
- Sandy Creek
- Shenango River
- Sugar Creek

NOTE:
Portions of this map that are provided for spatial reference only. They were generated from existing sources and may contain discrepancies that have not been corrected as part of this ACT 167 Plan.

DATA SOURCES:
Local Roads - PennDOT
Streams and Waterbodies - USGS NHD
Municipalities - PennDOT
Pennsylvania Counties - PennDOT
Ohio Counties - Ohio GIS
New York Counties - New York GIS
Major Highways - ESRI
Problem Areas - Crawford County
Stormwater Management Facilities - Crawford County

0.8 0 0.8 Miles

05/14/2010 R004384.0426

HRG
Hebert, Rowland & Greiner, Inc.
Engineering & Related Services

474 Windmere Drive
Suite 100
State College, PA 16801
814.238.7117
Fax 814.238.7126
www.hrginc.com
Offices Statewide

\\NAS0384020\Projects\Plate7A\Plate7A_Problems.mxd